


Model	Name	Article No.	Date	Revision	Revision date
FX Crown	Repair Kit Crown	9118	2020-01-24	EN.	


A




B




C



D



E



NO	ART. NO	DESCRIPTION	NO	ART. NO	DESCRIPTION
C1- 4.5	2529	O-ring 4,3 x 1,5 NBR 70	D29	19763	O-ring 9x1,5 NBR 90, <b>until serial no. 181700</b>
C1- 5.5	19726	O-ring 5,5 x 1,5 NBR 70	D29	19790	O-ring 10x1,5 NBR90, <b>from ser.no. 181700</b>
C1- 6.35	2575	O-ring 6,35 x 1,27 NBR 70	D30	4528	O-ring 7,66x1,78 NBR 70, <b>until ser. no. 181700</b>
C1- 7.62	19209	O-ring 7,5 x 1,5 NBR 70	D30	19225	O-ring 7,5x2 NBR70, <b>from ser.no. 181700</b>
C2	19703	O-ring 10x2 NBR 70	D32	19731	O-ring 2x1 NBR 90
D19	19950	O-ring 14x2 NBR 70	D34	11507	Rubbersteel washer M12
D20	19723-1	Plastic Washer, Thick, Regulator Gauge	D37	5109	O-ring 11,6x2,4 NBR 70
D23	5111	O-ring 2,5x1,5 NBR 90	D38	5111	O-ring 2,5x1,5 NBR 90
D24	16028	O-ring 12x1 NBR 70	D41	19929	Valvepin Crown CPL
D26	19109	O-ring 4x1,5 NBR 70	D42	19217	Valveseat CPL
D28	19109	O-ring 4x1,5 NBR 70	D46	19081	O-ring 11,1x1,6 NBR 70
			D48	19228	O-ring 6x2 NBR 70
			E1	5105	O-ring 9,3x2,4 NBR90